Resolution 2024-025 A Resolution Authorizing the Fiscal Officer to Pay Ohio Peterbilt for Maintenance and Repair to Engine 192 (Then & Now)

The following trustee □ Leez	e marked below seconded er	
		tion, and the vote was as follows:
Leezer: □ YES/ □ N	NO Fleshman: □ YES/	□ NO Blevins: □ YES/□ NO
Adopted on March 8, 2 Attested to on this 8th of Fiscal Officer, Linzie Ju	day of March 2024	Trustee James Leezer Trustee John Fleshman Trustee Mike Blevins

2

Resolution 2024-025 A Resolution Authorizing the Fiscal Officer to Pay Ohio Peterbilt for Maintenance and Repair to Engine 192 (Then & Now)

The Board of Trustees of Franklin Township, Franklin County, Ohio, met in person in a Regular Meeting at 12:00 p.m. on Thursday, March 8, 2024. The trustee marked below made a motion for the adoption of the following Resolution:

□ Leezer	□ Fleshman	□ Blevins

WHEREAS, in on February 16, 2024, Ohio Peterbilt provided repair and maintenance service to Engine 192; and,

WHEREAS, after product/services were rendered, the Township received invoice (#WO640006250) for which a purchase order, with prior certification of availability of appropriations and funds to pay the obligation by the Fiscal Officer did not reflect enough funds to pay invoice; and,

WHEREAS, Section 5705.41(D)(1), Revised Code, provides that in certain circumstances a subdivision may authorize payment on a contract executed without prior certification by the Fiscal Officer; and

WHEREAS, the Township's Board of Trustees now has before it a certificate from the Fiscal Officer certifying there was at the time of the making of that contract and at the time of the execution of such certificate a sufficient sum funds for the purpose of such contract and in the treasury or in process of collection to the credit of an appropriate fund free from any encumbrances (a "Then and Now certificate"); and,

WHEREAS less than thirty days have passed since the Township Board of Trustees' receipt of the certificate from the Fiscal Officer: and'

WHEREAS the Township Board of Trustees desires to satisfy the obligations on the contract.

NOW THEREFORE, BE IT RESOLVED BY THE BOARD OF TRUSTEES OF FRANKLIN TOWNSHIP, FRANKLIN COUNTY, OHIO, THAT:

Section 1. The Board of Trustees hereby acknowledges receipt of a "then and now certificate" from the Fiscal Officer and authorizes and directs the fiscal officer to make payment not to exceed the amount of \$9,938.03 to Ohio Peterbilt.

Section 2. That all formal actions of this Board concerning and relating to the adoption of this Resolution were passed in an open meeting of this Board, and that all deliberations of this Board and of any of its committees that resulted in such formal action, were in meetings open to the public, in compliance with all legal requirements including Section 121.22 of the Ohio Revised Code.

Section 3. That this Resolution shall be declared an emergency upon its adoption.

FRANKLIN TOWNSHIP 2024 PURCHASE REQUISITION FORM

DEPT:	· IRE	VENDOR: OH	O PETALBUILT	DATE: 2/2//2024
<u></u> Sτ.	ANDARD [BLANKET	SUPER BLANKET	THEN AND NOW 235
Quantity	Cost	, Extended Value	I.	Description
1		9938.03		WHELL REPAIRS FOR
Account Co	ode: 2191 22	20 323 3232	E192 (ARROW))
·			Even of the second of the seco	73%
Account Co	ode: 🏸 🛴		Printer of the second of the s	
Account Co	ode:		Triber and the second s	
			Grant Transferond Transferond Transferond	
Account Co	ode:		The distribution	alo till
	The second second	Transfer of the second		/
Account Co	ode:	AND PROPERTY AND A CONTROL OF THE PARTY OF T		3/7
	beg of Land Application and Ap	M		mosting
Account Co	de:			
	1	LA LA	74 76	en 4 lhow
Account Co	der [] \	TATE	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	ROMAN
		JVVJ		
Account Co	de:[:\CT		nklin Com	aty OH
Account Co	de:			
				New Selection (Control of Control
Account Co	<u> </u> de:	***************************************	1 1	
Signaturi				



Robyn Watkins

From:

Robert Arnold

Sent:

Wednesday, February 21, 2024 9:44 AM

To:

Robyn Watkins; Steven Mazer Then and Now PO request

Subject: Attachments:

DOC002 (8).pdf

Robyn,

Attached you will find a then and now PO request for repairs to E192...The initial quotes were within the amounts of my blanket PO for fire truck repairs. Unfortunately, the cost of the repairs is significantly higher than was initially estimated. Thank you for your understanding and patience with my short sightedness on this one! Let me know if you have any questions.

Respectfully,

Bob Arnold

Fire Chief Franklin Fire

Office: 614-279-1537 Cell: 614-214-8442



CONFIDENTIALITY NOTICE:

The contents of this email message and any attachments are intended solely for the addressee(s) and may contain confidential and/or privileged information and may be legally protected from disclosure. If you are not the intended recipient of this message or their agent, or if this message has been addressed to you in error, please immediately alert the sender by reply email and then delete this message and any attachments. If you are not the intended recipient, you are hereby notified that any use, dissemination, copying, or storage of this message or its attachments is strictly prohibited.





3993 E. Royalton Rd Broadview Hts, OH 44147

Service Invoice

Invoice Number:

WO6400006250

Page 1 of 5

Ref Doc:

64W6890

P.O. Number:

verbal

Invoice Amount:

\$9938.03 02/16/2024

Sold To: 3106937

Remit Payment To: Ohio Peterbilt P.O. Box 854439

Minneapolis, MN 55485-4349

Franklin Twp Fire Dept 4100 SULLIVANT AVENUE COLUMBUS, OH 43228

For Questions, please contact:

CARRIE KLINK 440-838-7443 CKLINK@OHIOCAT.COM

Customer #: 3106937
Equipment/Unit No.; E-192

<u>Equipment Offit (40.1 E-192</u>		Terms; 2
Make: Model: 2009	SN: 54F2CB617KMW12270 SMU/OD: 157598.0	ECM Reading:12813.0
	INVOICE SUMMARY:	

	INVOICE SUMMARY:						
SEG	DESCRIPTION	PARTS	LABOR	MISC	F/R ALL	ADJUST	TOTAL
1	Repairs or Diagnostics	291.63	720.00	0.00			1011.6
2	Repairs or Diagnostics	136.59	540.00	64.80			741.3
3	Repairs or Diagnostics	628.00	432.00	51.84			1111.8
4	General Accessories	75.73	864.00	0.00			939.7
7	Repairs or Diagnostics	5413.44	720.00	0.00			6133.4
	SUBTOTAL	6545.39	3276.00	116.64			9938.0
	TOTAL	6545.39	3276.00	116.64			9938.0

Peterbilt Ohio Peterbilt

PAY THIS AMOUNT

\$9938.03

PAYMENT TERMS - Net 30 Days from invoice date. A monthly Finance Charge up to 1.5% (16% APR) will be added on all past due amounts.

Service Invoice

Shipped To: Franklin Twp Fire Dept 4100 SULLIVANT AVE COLUMBUS OH 43228

Go Paperless. Receive statements and invoices online 24/7. Register at https://ohiocat.billtrust.com

Ohio Peterbilt Page 2 of 5

Service Invoice

3993 E. Royation Rd Broadview His, OH 44147

Invoice Number: WO6400006250

Ref Doc:

64W6890

P.O. Number:

verbal

Invoice Amount: **Invoice Date:**

\$9938.03 02/16/2024

Sold To: 3106937

Franklin Twp Fire Dept

DOMESTIC :		Kebairs	OI	Diagnostics
Complain	+ + CDM			

Cause: C-PM

Correction: Replaced fuel water filter. Changed oil and filter. replaced fuel filter, greased and inspected.

QUANTITY	PART NO	DESCRIPTION	UNIT PRICE	FXT	ENSION
8.00 1.00 1.00 1.00	15W40 FF5636FLG LF9009FLG P551103	15W40 BULK OIL FILTER-FUEL FILTER-OIL FILTER-FUEL/WATER SEPERATOR	21.98 22.62 39.36 53.81 TOTAL PARTS TOTAL LABOR TOTAL MISC CHGS SEGMENT 1 TOTAL	SEG. 1 SEG. 1 SEG. 1	175.84 22.62 39.36 53.81 291.63 720.00 0.00

SEGMENT 2 :

Repairs or Diagnostics

Complaint: Air leak- even while sits

Correction: quick release valve leaking had to manually by pass the park brake

valve and each brake chamber to rule out a backfeeding chamber.

found that the P/s rear brake chamber was blown.

Clamped rod down.

Removed clevis pin.

Removed chamber. Removed air lines.

Matched new chamber with old.

carried air fittings over to new brake chamber but the rear clamp

was in the way

clamped push rod and caged chamber then clocked the clamp and

finished installing air fittings
mounted the brake chamber but the center section needed clocked to line air fitting up with the air lines so i had to clamp push rod

and cage the chamber again and clock the center section

then i tightened the clamp up, hooked up the air lines, hooked up slack adjuster and released brakes and adjusted the slack adjusters

QUANTITY	PART NO	DESCRIPTION	UNIT PRICE	EXTENSION	
1.00	GC3030CW	CHAMBER-BRAKE 2.25" WELD CLEV 2.5"STROKE	136.59		136.59
1.00	ShopSupp	Shop Supplies Percentage	64.80 TOTAL PARTS	SEG. 2	64.80 136.59
			TOTAL LABOR	SEG. 2	540.00
			TOTAL MISC CHGS SEGMENT 2 TOTAL	SEG. 2	64.80
SEGMENT 3 :		Repairs or Diagnostics			741.39

Peterbilt

3993 E. Royalton Rd Broadview His, OH 44147

Service Invoice

Invoice Number:

WO6400006250

Page 3 of 5

Ref Doc:

64W6890

P.O. Number: **Invoice Amount:**

verbal

Invoice Date:

\$9938.03 02/16/2024

Sold To: 3106937

Franklin Twp Fire Dept

Complaint: replace crankcase breather and valve cover gasket Correction: Replaced crankcase vent.

Cleaned egr crossover mounting surfaces. Installed egr crossover with new gaskets.

needs tubes replaced; had to pull lots of coolant lines back to be able to pop the connection off finally got my hand in there removed connector and pulled back. started at the top removed the bolt that hold unit in and removed the air pipe tub and pulled the whole unit up and fished it out

installed new one fished down in and behind lines to get to hosed connection and secured unit put bolt back in and hooked up air tube.

QUANTITY	PART NO	DESCRIPTION	UNIT PRICE	EXTEN	NSION
1.00 2.00 1.00 1.00 1.00	3959798CUM 4932615CUM 5255739 5263986CUM ShopSupp	GASKET, VALVE COVER GASKET, CONNECTION TUBE, BREATHER BREATHER, CRANKCASE Shop Supplies Percentage	53.26 5.38 94.81 469.17 51.84 TOTAL PARTS TOTAL LABOR TOTAL MISC CHGS SEGMENT 3 TOTAL	SEG. 3 SEG. 3 SEG. 3	53.26 10.76 94.81 469.17 51.84 628.00 432.00 51.84

SEGMENT 4 :

General Accessories

Complaint: replace the oil pan gasket Correction: Removed front skid plates.

Removed oil pan.

Cleaned oil pan.

Starting scraping old gasket off block,

QUANTITY	PART NO	DESCRIPTION	UNIT PRICE	EXTENS	ON
1.00	5332563CUM	GASKET, OIL PAN	75.73	47,410	75.73
			TOTAL PARTS	SEG. 4	75,73
			TOTAL LABOR	SEG. 4	864.00
			TOTAL MISC CHGS	SEG. 4	0.00
			SEGMENT 4 TOTAL		939.73

SEGNENT 7 :

Repairs or Diagnostics

Complaint: REPLACE THE FRONT RT WHEEL SEAL, BOTH FRONT ROTORS AND PADS

Correction: JACKED UP FRONT END. REMOVED WHEELS. REMOVED CALIPERS ON BOTH SIDES AND PAD PINS. FOUGHT THE ENTIRE WAY OUT ON BOTH SIDES. REMOVED THE PASS SIDE WHEEL HUB (THIS WILL BE REPLACED. IT WILL NOT STOP LEAKING. COULD BE CRACKED INTERNALLY AND BUILDING PRESSURE. HAS HAD 3 CAPS). REMOVED DRIVER SIDE HUB AND ROTOR. CLEANED ALL PARTS.

Peterbilt Ohio
Peterbilt

Page 4 of 5

Service Invoice

3993 E. Royalton Rd Broadview His, OH 44147 Invoice Number:

WO6400006250

Ref Doc:

64W6890

P.O. Number: Invoice Amount:

verbal

Invoice Date:

\$9938.03 02/16/2024

Sold To: 3106937

Franklin Twp Fire Dept

INSTALLED NEW ROTOR ONTO D/S HUB, REPLACED WHEEL SEAL AND TORQUED THE SPINDLE NUT TO SPEC. NEW PASS SIDE HUB DID NOT COME WITH RACES OR BEARINGS INSTALLED. HAD TO ORDER BEARINGS.WOULD DAMAGE RACES IF TRY AND REUSE. INSTALLED NEW RACES AND BEARINGS ON PASS SIDE. INSTALLED ROTOR ONTO NEW HUB FOR PASS SIDE. INSTALLED NEW WHEEL SEAL, INSTALLED HUB AND TORQUED SPINDLE NUT TO SPEC. PRE OILED BEARINGS BOTH SIDES BEFORE INSTALL.

INSTALLED NEW BRAKE PADS ON BOTH SIDES. TORQUED ROTOR TO HUB AND PAD

PIN BOLTS TO SPEC. REPLACED HUB CAPS AND TORQUED TO SPEC. FILLED HUBS WITH OIL. TOOK OFF JACK STANDS AND SET DOWN. TEST DROVE UNIT AND CHECKED FOR LEAKS. TOPPED OFF HUB OIL

QUANTITY	PART NO	DESCRIPTION	UNIT PRICE	EXTENSION
1.00	1202835	Bearing Cone	104.30	104.30
1.00	1202839	Cone Bearing	134.18	134.18
1.00	1202840	Cup Bearing	75.06	75.06
1.00	1237707	Brake Pad Set	567.89	567.89
2.00	1237720	ROTOR 22.5	1318.89	2637.78
1.00	1612CHR	HUBCAP-STEER OIL	33.98	33.98
1.00	1612CHR	HUBCAP-STEER OIL	33.81	33.81
1.00	2264320	Cup Bearing	57.86	57.86
10.00	2657156	Stud, Wheel 22M	10.37	103.70
2.00	3064863	Wheel seal Steer	58.30	116.60
1.00	3391989	HUB NON DRIVE	994.86	994.86
1.00	43764CHR	SEAL-OIL, SCOTSEAL CLASSIC TRAILER	59.81	59.81
1.00	FREIGHT	FREIGHT CHARGE	146.74	146.74
1.00	Freight	Freight ND	346.87	346.87
			TOTAL PARTS SEG.	i i
ļ			TOTAL LABOR SEG.	7 720.00
			TOTAL MISC CHGS SEG.	7 0.00
W0640000625	0		SEGMENT 7 TOTAL	6133.44

LIMITED WARRANTY

Ohio Machinery Co. warrants all service performed by its service personnel and all OEM parts provided in connection with such service to be free of workmanship defects for a period of six (6) months or one thousand five hundred (1,500) hours of operation, whichever comes first.

Ohio Machinery Co. will repair or replace, at its option, any damaged part involved in the warranty repair.

Unless otherwise agreed by Ohio Machinery Co., such parts and installation labor will be provided without charge to the OWNER/OPERATOR at Ohio Machinery Co.'s facility or at such other service establishment previously authorized by Ohio Machinery Co. at the option of Ohio Machinery Co.

Such repair service is to be provided during provider's regular business hours. OWNER/OPERATOR shall be responsible for all transportation cost associated with transporting the equipment to the site where such repairs are to be performed.

THIS WARRANTY IS NOT APPLICABLE TO FAILURES OR DEFECT RESULTING FROM:

- (a) The use of attachments not sold or approved by Ohio Machinery Co.; or
- (b) Installation of components or other repair work not performed by Ohio Machinery Co., which, in the judgment of Ohio Machinery Co., is deemed improper, or
- (c) Poor maintenance or abusive operation; or
- (d) An application that exceeds the specified limits in the manufacturer specification.

All repairs made by Ohio Machinery Co. pursuant to this warranty shall not extend the stated warranty period and the owner/operator shall be responsible for giving prompt written notice of warrantable failure and promptly making the machine available for repair.

In the event of breach of the above warranty, it is expressly understood that the owner/operator's sole remedy shall be the repair or replacement of any damaged part as specifically provided in this warranty, provided, however, that should the parts prove so damaged as to preclude the remedying of warranted workmanship defects by repair or replacement the owner/operator's sole and exclusive remedy shall then be refund of the purchase price of the parts and labor previously furnished or provided by Ohlo Machinery Co.

THE ONLY WARRANTIES APPLYING TO THIS PART(S) ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER. THE SELLING DEALER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHNTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS PART(S) AND/OR SERVICE, BUYER SHALL NOT BE ENTITLED TO RECOVER FROM THE SELLING DEALER ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT, OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

CONDITIONS AND LIMITATIONS:

With the above warranties and limitations understood, Ohlo Machinery Co. shall in no event be liable for any other losses, damages, costs or expenses claimed by the owner/operator, including but not limited to loss from failure of the equipment to operate for any period of time or business interruption, and all other direct, indirect, special, incidental, punktive or consequential damages, including but not limited to lost revenues, lost profits and indirect income loss, regardless of whether such claim is brought under breach of contract, breach of warranty, tort, strict liability, negligence or other theory of law or equity.

INDEMNIFICATION:

in the event that any services performed under this Work Order Invoice are performed at OWNER/OPERATOR'S facility or worksite, OWNER/OPERATOR shall Indemnify, defend and hold harmless Ohio Machinery Co. from any damages to property or personal injury suffered by Ohio Machinery Co. and/or its personnel occurring while on the site of OWNER/OPERATOR'S facility or worksite (except to the extent caused by the negligent or willful actions of Ohio Machinery Co. or its personnel), and Ohio Machinery Co. shall indemnify, defend and hold harmless OWNER/OPERATOR for damages to property and personal injury caused by the negligent or willful actions of Ohio Machinery Co. or its personnel.

THE WARRANTY SET FORTH ABOVE IS GIVEN IN LIEU OF ALL OTHER WARRANTIES EXPRESS OR IMPLIED AND ALL OTHER WARRANTS ARE HEREBY DISCLAIMED, INCLUDING WITHOUT LIMITATION LIMITING THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR ANY PARTICULAR PURPOSE.

; ;			
The state of the s			
Medical Control			
<u>;</u>			
1			
-			
-			

- -0500

Ohio Peterbilt - Grove City PB

6240 Enterprise Pkwy Grove City, Ohio 43123 Phone: (614) 875-3732



Case Number: 14672537 Repair Order Number: 6890 Purchase Order Number: N/A

Service Advisor: Kennedy, *Dominica - Case Date 2024-02-01 08:34:58 -0500 ETR: 2/11/2024 at 08:37 am EST

Customer: Franklin Twp Fire Dept	Unit Number: E-192
Address: 4100 SULLIVANT AVE COLUMBUS, OH 43228 Phone: (614) 279-0089 Fax: N/A Customer Number: 3106937	Asset: 2010 PIERCE MANUFACTURING ARROW XT Serial Number: 1AA011125 VIN: 4P1CA01A1AA011125 Engine: ISL Engine Hours: 12813 Odometer: 157598 Miles 1AA01111 Warranty Start: N/A In Service: N/A

			*
iten	Operation Name		Additional Totals
1	C-PM	X357650.	Additional Totals Charges
	Complaint:		
	C-PM		
	Cause:		
	C-PM		
	Correction:		
	Replaced fuel water filter. Changed oil and filter, replaced fuel filter, greased and ins	helped	
	Labor.		*
	Parts:		\$720.00
	-(1.0) FILTER-LUBE		\$341.78
	-(1.0) FILTER ASSY-LIQUID SPIN-ON FUEL -(1.0) FILTER-FUEL/WATER SEPERATOR		
	-(8.0) ENGINE OIL		
(disermited-sy	POWER CONTINUES AND ASSESSMENT OF THE PROPERTY		
2	replace the front rt wheel seal and both front brake rotors and pads	大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大	Professional Commence of the House of the Commence of the Professional Commence of the Commenc
	Complaint:		
	REPLACE THE FRONT RT WHEEL SEAL, BOTH FRONT ROTORS AND PADS		
	Correction:		
	JACKED UP FRONT END. REMOVED WHEELS. REMOVED CALIPERS ON BOTH ENTIRE WAY OUT ON BOTH SIDES. REMOVED THE PASS SIDE WAYER HAD A	SIDES AND PAD PINS FOUGHT THE	
	STOP LEAKING COULD BE CHACKET MEETING (HIS WILL BE REPLACED. IT WILL NOT	
	SIDE HUB AND ROTOR CLEANED ALL PARTY INSTALLED NEW TOTAL	- HAS HAD 3 CAPS). REMOVED DRIVER	
	TORQUED THE SPINDLE NUT TO SPEC. NEW PASS SIDE HUB DID NOT HAD TO ORDER BEABINGS. WOULD DAMAGE PAGES IF TRY AND PERFORMENT.	WITH BACES OR BEARINGS INSTALLED	
	PASS SIDE. INSTALLED BOTOR ONTO NEW HUND TOP BASS SIDE.	ALLED NEW RACES AND BEARINGS ON	
	TORQUED SPINDLE NUT TO SPEC PRE OILED BEARINGS BOTH SIDES BEFOR	E W WHEEL SEAL, INSTALLED HUB AND	
ı	INSTALLED NEW BRAKE PADS ON BOTH SIDES. TORQUED ROTOR TO HUB ANI HUB CAPS AND TORQUED TO SPEC, FILLED HUBS WITH OIL. TOOK OFF JACK UNIT AND CHECKED FOR LEAKS, TOPPED OFF HUB OIL) PAD PIN BOLTS TO SPEC. REPLACED	
,	UNIT AND CHECKED FOR LEAKS, TOPPED OFF HUB OIL	STANDS AND SET DOWN, TEST DROVE	
	Laboří, 170		
-	Parts:	,	\$720.00
	(1.0) HUBCAP STEER OIL (2.0) WHEEL SEALS		\$3,958.22
	(2.0) BRAKE ROTORS		
	(1.0) BRAKE PAD SET		
	(2.0) HUBCAP-STEER OIL		
	(1.0) SEAL-OIL, SCOTSEAL CLASSIC TRAILER		
-((1.0) CONE BEARING		
-((1.0) BEARING CONE		
	(1.0) CUP BEARING		
	(1.0) CUP BEARING	,	
-((10.0) WHEEL STUDS		

Cause:				
C-PM				
Correction:				
Replaced fuel water filter. Ch	nanged oil and filter, replaced fue	l filter greased and increased		
Labor:	,	and inspected.		
Parts:				\$720.00
-(1.0) FILTER-LUBE			k a	\$341.78
-(1.0) FILTER ASSY-LIQUID	SPIN-ON FUEL			
-(1.0) FILTER-FUEL/WATER	SEPERATOR			
-(8.0) ENGINE OIL	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)			
2 replace the front rt wheel sea	al and both front brake rotors and		CANANT LI MANINE LINE E ENTEN NE STANDATION RESEARCE CONDUCTOR WAS WASTERNING OF A PERSON OF ALL LAND ENTEN FO	等于是否则是是工程中的企业的实验的企业的,从2016年2016年2016年2016年2016年2016年2016年2016年
Complaint:	A CONTROLL DIAMESTO DISS AND	pags		
REPLACE THE FRONT RT V	WHEEL SEAL, BOTH PRONT RO	OTO DO SAUD DA - 0		
Correction:	THE SEAL, BOTH FROM THE	JIOHS AND PADS		
	EMOVED THEFT OF DEVICE			
ENTIRE WAY OUT ON BOTH	EMOVED WHEELS, REMOVED	CALIPERS ON BOTH SIDES	AND PAD PINS. FOUGHT THE L BE REPLACED. IT WILL NOT	
STOP LEAKING COULD BE	CHACKED METERNALLY AND -	ODE MUEER URB (1412 MIT	L BE REPLACED. IT WILL NOT	
TOROUGH THE SHADE	EANED ALL PARTS INSTALLED	NEW ROTOR ONTO DIS HUE	AD 3 CAPS). REMOVED DRIVER 3,REPLACED WHEEL SEAL AND	
HAD TO ORDER BEARINGS	WOLLD DAMAGE BACEOUS	LOD DID LIOT COME MILL BY	ACES OR BEARINGS INSTALLED.	
PASS SIDE, INSTALLED BOT	TOR ONTO MEW HUNDED DAG	THAND REUSE. INSTALLED	NEW RACES AND BEARINGS ON	
TORQUED SPINDLE NUT TO	SPEC PRE OILED BEARINGS	S BOTH SIDES BEFORE INST	EEL SEAL, INSTALLED HUB AND ALT	
HUB CAPS AND TORQUED	TO SPEC. FILLED HURS WITH	D ROTOR TO HUB AND PAD F	PIN BOLTS TO SPEC. REPLACED 3 AND SET DOWN. TEST DROVE	
UNIT AND CHECKED FOR L	EAKS. TOPPED OFF HUB OIL	OIL. TOOK OFF JACK STANDS	S AND SET DOWN. TEST DROVE	
Labor:				
Parts:			,	\$720.00
-(1.0) HUBCAP STEER OIL	*			\$3,958.22
-(2.0) WHEEL SEALS				
-(2.0) BRAKE ROTORS				
-(1.0) BRAKE PADÎSET				
-(2.0) HUBCAP-STEER OIL				
-(1.0) SEAL-OIL, SCOTSEAL	CLASSIC TRAILER			
-(1.0) CONE BEARING				
-(1.0) BEARING CONE				
-(1.0) CUP BEARING			,	
-(1.0) CUP BEARING				
-(10.0) WHEEL STUDS				
hio Peterbilt - Grove City I	PB			
, .				
The state of the s			4 · · · · · ·	· · · · · · · · · · · · · · · · · ·

Will have been seen as a second secon	and the
Peterbilt - Grove City PB	
-(10.0) WHEEL STUDS	
-(1.0) CUP BEARING	•
-(1.0) CUP BEARING	
-(1.0) BEARING CONE	
-(1.0) CONE BEARING	
-(1.0) SEAL-OIL, SCOTSEAL CLASSIC TRAILER	
-(2.0) HUBCAP-STEER OIL	
-(1.0) BRAKE PAD SET	
-(2.0) BRAKE ROTORS	

Ohio Peterbilt - Grove City PB

Customan E	Unit Number: E-192	
THE EMPIREMENTAL SHEET OF THE SECOND STATE OF	The state of the s	4
Case Number: 14672537	Asset: 2010 PIERCE MANUFACTURING ARROW XT	2
	VIN: 4P1CA01A1AA011125	1



Item	Operation Name	Additional Totals
-(2.0) WHEEL SEAL		Additional Totals Charges
	A	
		Parts: \$4,300.00
		Labor: \$1,440.00
		Freight: \$493.61
		Total: \$6,233.61

[2/1/2024 at 08:38 am EST] - Unit E-192 was checked in at Ohio Peterbilt - Grove City PB. Arrival time: 2/1/2024 at 08:37 am EST. Case status set to Checked-in.
[2/13/2024 at 01:31 pm EST] - PICKING UP TODAY

lte				
1	Declined or Deferred Operation ***UNIT NEEDS PARKED INSIDE***	Labor	Price	Status
2	784 A SECTION ASSESSMENT (ALCOHOLOGY / BANK	\$0.00	\$0.00	not sold
-	replace the oil pan gasket Parts: - (1.0) GASKET,OIL PAN	\$864.00	\$75.66	not sold
3			\$75.66	
-	Air leak- even while unit sits- ABQVE REAR AXLE Parts: - (1.0) CHAMBER-BRAKE 2.25" WELD CLEV 2.5"STROKE	\$540.00	\$136.73	not sold
4	WAS INVESTIGATED TO THE PROPERTY OF THE PROPER		\$136.73	
7	replace valve cover Gaskef and crankcase breather Parts: - (1,0) GASKET, VALVE COVER	\$432.00	\$629.73	not sold
	: (I.O) BREATHER, CRANKOASE		\$53.26	
	(1,0) TUBE BREATHER		\$469.17	
	(1.0) GASKET, CONNECTION		\$101.92	
			\$5.38	

Ohio Peterbilt - Grove City PB